

Harris Gas Guard Plus



The Harris Gas Guard Plus unit is designed for use with all shielding gas welding applications reducing "Back Pressure Surge" offering potential shielding gas cost savings of up to 50%.

It is specifically designed for applications where a long shielding gas supply hose is in use such as MIG machines with separate wire feeders and Robots.

Part Number - 4404948

Features:

- Encased in a steel enclosure box for extra protection.
- Enclosure box has a lockable door with window.
- Magnetic fixing or mechanical option.
- Supplied with inlet and outlet nut & hose connections.
- Supplied with lock keys.
- Supplied with Allen / Hex key for torch flow adjustment.



How to use:

- Fix Gas Guard Plus unit to the feeder / machine, connect gas supply to the inlet, then a short hose from the outlet to the feeder/machine gas inlet.
- Adjust gas supply from the Gas Guard Plus using the Allen / Hex key provided so that correct flow rate required is measured at the torch outlet.
- The Gas Guard Plus door can be locked to stop any changes to the flow rate being made once it is set.



Distributed By

Lincoln Electric (UK) Limited,
Mansfield Road,
Aston,
Sheffield,
South Yorkshire, S26 2BS
Phone: +44(0)114 287 2401
salesuk@lincolnelectric.eu
www.lincolnelectric.eu

